

# BOSS ME-80 Guitar Multiple Effects

DC IN POWER USB COMPUTER AUX IN REC OUT/PHONES

L/MONO R Gt. AMP OUTPUT GUITAR INPUT

### PREAMP

STACK DRIVE LEAD COMBO CRUNCH TWEEED CLEAN AC

METAL GAIN 11 BASS 22 MIDDLE 33 TREBLE 44 LEVEL 55

### EQ/FX2

PHASER TREMOLO BOOST DELAY CHORUS EQ

RATE/TIME 50 DEPTH/FB 50 LEVEL 50

BASS MIDDLE TREBLE LEVEL

### REVERB

HALL 50

ROOM SPRING

### COMP/FX1

DEFRETTER SLOW GEAR OCTAVE T. WAH DOWN T. WAH UP COMP SUSTAIN/SENS/-1OCT ATTACK/TONE/-2OCT LEVEL/PEAK/DIRECT

RING MOD AC SIM Single ▶ Hum Hum ▶ Single SOLO

50 50 50

FREQ/LOW D. LEVEL/HIGH E. LEVEL/LEVEL

### OD/DS

DISTORTION TURBO OD BLUES T-SCREAM OVERDRIVE BOOST

TURBO DS METAL DS CORE FUZZ OCT FUZZ

DRIVE 50 TONE 50 LEVEL 50

### MOD

PITCH SHIFT VIBRATO CHORUS TREMOLO FLANGER PHASER

HARMONIST ROTARY UNI-V DELAY OVERTONE

RATE/KEY DEPTH/HARMONY E. LEVEL/RESONANCE

50 50 50

UPPER LOWER D. LEVEL

### DELAY

MODULATE TAPE ANALOG 500-6000ms 100-600ms 1-99ms

REVERSE CHO + DELAY [TEMPO] TERA ECHO PHRASE LOOP

TIME 50 FEEDBACK 50 E. LEVEL 50

BATTERY LOW

EXIT WRITE CTL EDIT NS: HOLD+BANK

OUTPUT LEVEL 50

### PEDAL FX

FREEZE -1OCT +2OCT +1OCT VOICE WAH OSC DELAY OD/DS MOD RATE DELAY LEV

BANK AMP

1 COMP

BANK EQ

2 OD/DS

CTL REV

3 MOD

SET TEMPO PRESS & HOLD > 2 SEC

MEMORY

TUNER PRESS & HOLD > 2 SEC

MANUAL

4 DELAY

SET TEMPO/OFF PRESS & HOLD > 2 SEC

COSM